

● 位置図



※表示は本線部分の運送を表したものです
※模式図のため現場状況と一致しない場合があります

九頭龍IC 油坂出入

かいざら

はこがせ

法面びび割れ発生箇所

法面びび



学識経験者による現地診断

学識経験者による現地診断

かみはんばら

An aerial photograph of a ski resort in winter. The landscape is covered in snow, with dark evergreen trees scattered throughout. A prominent ski lift track runs diagonally across the frame. Several buildings, including a large white structure and smaller lodges, are visible. A road with parked cars is in the lower right corner.

An aerial photograph showing a collapsed bridge structure in a snowy, wooded area. The bridge deck is partially visible, supported by a large, cylindrical concrete pier. The surrounding landscape is covered in snow, and the bridge structure appears damaged and partially submerged in the snow.